UNCLASSIFIED

AD 263 382

Reproduced by the

ARMED SERVICES TECHNICAL INFORMATION AGENCY ARLINGTON HALL STATION ARLINGTON 12, VIRGINIA



UNCLASSIFIED


263382



NECAD DIVISION BOBLE-NATIONAL BATTERIES, INC.

NOTICE: When government or other drawings, specifications or other data are used for any purpose other than in connection with a definituly related government procurement operation, the U. S. Government thereby incurs no responsibility, nor any obligation whatsoever; and the fact that the Government may have formulated, furnished, or in any way supplied the said drawings, specifications, or other data is not to be regarded by implication or otherwise as in any manner licensing the holder or any other person or corporation, or conveying any rights or permission to manufacture, use or sell any patented invention that may in any way be related thereto.

Vented Nickel-Cadmium E-41
Alarm Battery (Development Models)
Supplementary Report
August 1, 1960 to March 31, 1961
Signal Corps Contract No. DA 36-039 SC-85273
DA Project No. 3G18-03-001
Signal Corps Technical Requirement
SCL-6837, 5 October 1959
U.S. Army Signal Research and
Development Laboratory
Fort Monmouth, New Jersey
Gould-National Batteries, Inc.
NICAD Division
Easthampton, Mass.



Supplementary Report

t.

Vented Nickel-Cadmium E-41 Alarm Battery (Development Models)

Signal Corps Contract No. DA 36-039-SC-85273
Signal Corps Technical Requirement SCL-6837
DA Project No. 3618-03-001

August 1, 1960 to Harch 31, 1961

The life cycle testing of vented nickelcadmium batteries for the E-41 Alarm

Propared by

1

ī

Stanley Januszkiewicz, Project Engineer

NICAD DIVISION
GOULD_NATIONAL BATTERIES, INC.
EASTHAMPTON, MASS.

TABLE OF CONTENTS

	Text		Page
	1.	Purpose	1
	2.	Abstract	1
	3.	Conferences	2
ı	4.	Factual Data	3-11
		a. Introduction	3-4
		b. Apparatus	4-5
		c. Cycling Tests	5-11
	5.	Conclusions	12
	ζ,	Reconsendations	12
•	7.	Personnel	12
•		ondix	

=

- 5

TABLE OF CONTENTS (CON'T)

No. 1 2	Tables Cycling Test Results Automatic Cycling Times	Page 6-7 9
No. 1 Appendix	Figures Charge - Discharge Circuits Diagram	Page 5a
NICAD Drawing Ho. CPA-2805-1 CPA-3805-8	NICAD DRAWINGS Title Cycling Test Panel (Front) Cycling Test Wiring	

1. PURPOSE

The purpose of the test was to determine whether the vented nickel-cadmium battery for the E-41 Alarm would withstand two hundred (200) cycles as specified in Amendment No. 1, SCL-6837.

ABSTRACT

A cycling unit was designed and built to perform the life cycle tests on the E-41 alarm battery. Considerable electrical trouble was experienced with the motor generator charging source.

d. The initial battery capacities were lower than expected from our previous acceptance test data. This was traced to insufficient overcharge of the positive plate.

d. In view of the fact that the attainment of complete charge of the positive plates after the capacity cycle could not be readily accomplished by extending the constant potential charge to four (4) hours, this charge was changed to constant current.

d. The batteries successfully passed the two hundred (200) charge - discharge cycles.

3. CONFERENCES

(i) At Gould-National Batteries, Inc., Easthampton, Mass., Mr. S. Januszkiewicz of Gould-National Batteries, Inc., Messrs. T. Strozyk and M. Pockop of Chemical Warfare, and Mrs. S. Duze of U. S. Army Research and Development Laboratories - February 16, 1961.

Concurrent cycling tests by the Chemical Corps that had exceeded two hundred (200) cycles were discussed. These were carried out manually with each discharge proceeding to 20.00 volts. It had been found necessary to introduce occasional constant potential charges of four (4) hours in order to recover small capacity losses on cycling.

4. FACTUAL DATA

1

a. Introduction

The original contract proposal (SCI_6837; 5 October 1959) stipulated that the battery undergo 200 cycles of charge and discharge at 80°F. This battery for the E_41 alarm consists of 20 NICAD - CCK5XMN cells, having a nominal 6 A.H. of capacity. The schedule called for one (1) cycle to be performed every twenty-four (24) hours according to the following sequences:

- "a. Charge at the five (5) hour rate for 7 hours.
- b. Battery on open circuit shall stand for $2\frac{1}{2}$ hours.
- c. Discharge at 0.500 ampere for 12 hours.
- d. Battery on open circuit stand for 2 hours.
- e. On every 14th cycle, the battery shall be discharged at 0.500 ampore to 20 volts, and on the succeeding cycle recharged at the five (5) hour rate to 140, of the capacity removed.
- f. The total elapsed time for steps (a) to (d) shall be 24 hours.

 For step (e) the open circuit time may be adjusted so that each cycle lasts 24 hours."

This schedule was modified as follows by SCL-6837 - Amendment No. 1, 29 January 1960

- "a. Charge at a constant potential of 31.0 1 1% volts (1.55 volts per cell) for two (2) hours.
- b. Battery on open circuit stand for five (5) hours.
- c. Discharge at 0.500 ampere for twelve (12) hours.
- d. Battery on open circuit stand for five (5) hours.
- e. On every 14th cycle, the battery shall be discharged at 0.500 ampere to 20.0 volts and on the succeeding cycle recharged at 31.0 ± 1% volts (1.55 volts per cell) for four (4) hours.

f. The total elapsed time for steps (a) to (d) shall be twenty-four (24) hours. For step (e) the open circuit time may be adjusted so that each cycle lasts twenty-four (24) hours."

In addition to the change in the cycling schedule, the amendment provided for the method of selection of the batteries. This was based upon the lot size of the batteries - if under 66, one (1) per lot; if 66-200, two (2) per lot. Also provided for was an adjustment schedule in the contract if the batteries failed the required life tests.

b. Apparatus

Ž.

The cycling apparatus to fulfill the requirements of the cycling schedule was custom designed and built at NICAD. A detailed description of the panel is presented in the attached NICAD Drawings - CPA-3805-1. ..8.

The cycling board consists of two (2) identical units in parallel.

Each board operates independently of the other except for their common charging source and timer on which independent cams are driven by the same motor unit. The operation of the board can be made either automatic or manual by merely changing the switches located on the panel board.

The charging source was a General Electric Aircraft Energizer Model 5BY203AL: 14-35 Volts Direct Current; 265 Amperes Continuous; 500 Amperes Intermittent. The voltage controls were rewired to allow adjustment at the front of the cycling panel. Although this unit was purchased as a reconditioned item it gave considerable mechanical trouble. During the course of the cycling, it was necessary to replace the voltage regulator and brushes, resurface the motor due to poor contact of the voltage regulation brush, and replace the field coils due to an internal short. As can be intimated from the above, the greatest difficulty during the cycling test was the most critical unit, the charging source.

The cycling timer was Model MC-12 made by Industrial Timer Corp.,

Newark, New Jersey. This timer makes one (1) revolution every 24 hours. The operation of each battery is controlled by two (2) cams, one for charging and the other for discharging. The operation of charge, discharge and open circuit is controlled by energizing mercury relay switches on the panel. Although this timer is satisfactory for the required cycling schedule, the use of a more elaborate timer would be justified to allow the easy changeover to other cycling schedules, as for example (after every for teenth (14th) cycle,).

The layout of the charge and discharge circuits is readily understood. The charge circuit from busbar to busbar as in Figure I consists of the battery, a Recdo Model 16 (0-50) ammeter; a Weston 50 ampere-shunt; a Struthers - Dunn Inc. mercury relay, type 48AXX3, contact rating 45 ampere - 115 volts A.C.; a S.P.S.T. 60 ampere manual switch; and a 50 ampere fuse. The wiring was made as large as practical to decrease the chmic resistance losses between the busbar voltage and the battery terminals. The discharge circuit as in Figure I consists of the battery, a Beede Model 16 (0-1) ammeter; a Weston 1 ampere shunt; a Ebert Electronic Inc., mercury relay, Type HD-1, contact rating 12 amperes 115 volt D.C.; a S.P.S.T. 12 ampere manual switch; a 1 ampere fuse; and two (2) Jagabi resistors in series, one 88 chms - 1.2 amperes and the other 11 ohms - 5.0 amperes.

c. Cycling Test

()

The batteries for the cycling test selected by the Signal Corps were Nos. 28 and 83 from Lot Nos. 2 and 3 respectively. They were subjected to cycling as per the amended schedule. As a matter of practice, the discharge was started at 8:00 A.M. In several instances where it was desired to check time variations on battery capacity, the discharge rate was doubled so that the discharge could be completed within the normal work day. A complete summary of capacity cycles is presented in Table No. 1.




FIGURE 1

CHARGE - DISCHARGE CIRCUITS - DIAGRAM

:

€)

Table No. 1

Cycling Test Results

Discharge Capacity A.H. to 1.00 Volt/Cell .28	19•9	6.31	6.25 (1) 7.11	(2) 62.9	0 1 9	6.09 7.10	7-35 (3)	7.24	6.85	6.73	45.9	6.95	6.61	6•43	₹°9
Discharge Capacity A. .28	₹8*9	6.52	6.50	6.37	6.53	6.28 7.41	09*2	7.39	7.02	86*9	6.73	7.10	5.35	6.25	6.83
Duscharge Current Apperes	1.6	6.0	1.0	5.0	6.0	1.0	0.5	0.5	0.5	0.5	0.5	5.0	5.0	6.0	6.0
Charge	1.55 V/Cell - 4 hours	1.55 V/Cell - 2 hcurs	1.55 V/Cell - 2 hours 1.55 V/Cell - 2 hours	1.55 V/Cell - 2 hours	1.55 V/Cell - 2 hours	1.55 V/Cell - 2 hours 0.8 ampere - 16 hours	1.55 V/Cell - 2 hours	1,55 V/Cell - 2 hours	1.55 V/Cell - 2 hours	1.55 V/Cell - 2 hours					
Cycle No.	H	14	19	28	745	£23	26	2	₫	88	217	126	140	154	168

()

1.00 Volt/cell	6.19 (4)	6.58 (5)	6.35
Discharge Capacity A.H. to 1.00 Volt/cell	60.9	6.31	6.08
Discharge Current Lysres	3.5	0.5	٠.
Charge	1.55 V/Cell - 2 hours	1.55 V/Cell - 2 hours	· ;>
Sycle No.	182	304	201

lotes:

- Discharge continued for a total of eight hours. Adjustment made in time cycle to insure full two (2) hours of charge. (T)
- After 35 cycles, voltage of generator could not exceed 28 volts. The difficulty was located in voltage regulator. This is believed cause of low voltage on charge. Then set in P.M. voltage was at specified 31.0 volts. In A.M. of next day voltage down to 30.0 30.2 volts. (5)
 - After this cycle, batteries were charged at one (1) ampere for approximately 10 hours. procedure repeated on cycle following succeeding capacity cycles. ව
- (4) Fower shut off over week-end.
- (5) Generator trouble due to shoft in field wirdings.

| では | 1985年 | 1985年

A compared to the second of th

The cells were subjected to an initial cycle capacity test after a four (4) hour charge at 1.55 volts/cell. The battery capacities were on the low side both with respect to the desired initial capacity and that previously found during the acceptance tests. Previous experience had indicated that with continued overcharge on cycling the capacity of the cells would improve.

4

The fourteenth cycle capacity discharge did not show any improvement so a check was made of the time cycle which was recorded with an Esterline-Angus Model AW Recording Ammeter modified for use as a voltmeter. It was found that several time adjustments were required. Table No. II indicates the actual time cycles before and after adjustment. In addition there are presented the times at the end of cycling. It can be seen that the cycling times fulfill the specification requirement within the limits of the adjustment that can be made on the small cams. It had also been observed that although the voltage was properly set at 31.0 volts before leaving at night, in the morning it would be between 30.0 and 30.2 volts.

A recheck of the capacity on the nineteenth (19th) cycle indicated that there had not been a capacity improvement with the adjusted charge time. The batteries were discharged for a total of eight hours using an external voltage to equalize the cells. This resulted in a substantial increase in capacity on the next cycle as shown in Table No. 1. On the twenty-eighth (28th) cycle, the cell capacities were again low since considerable trouble was experienced with the charging voltage.

After the thirty-fifth (35th) cycle, the voltage regulator broke down in a way that did not allow the charge voltage to exceed 28 volts. Inasmuch as this occurred during the weekend, these three cycles were discarded. The batteries were left in the discharged state while the generator was being repaired.

Table No. II ... utoratic Cycling Times

<u>,</u>)

				•	\$1		
Battery			28		%. 83	33	
	Specification	Before Adjustment	liter Adjustment	End of Cycling	Before Adjustment	After Adjustment	End of Cycling
Charge	2-0 (1)	1-56	2-7	2-52	1-53	2-6	5-6
Cpen Circuit	5-0	5-2	67-7	1777-77	5-27	5-16	5-2
Discharse	12-0	12-19	12-23	12-3	22-22	12-31	11-59
Open Circuit	24	24-4	€23 ¥	177-17	4-26	4-26	4-53

(1) Time is referred to as 2 hours - 0 minutes

The cycling was then resumed using only the regular two hour charge at 1.55 volts/cell. A recheck of capacity was made on the fifty-third (53rd) cycle to determine if the capacity had improved with the repair of the generator. In view of the fact that the capacity was marginal, the cells were given a constant current charge to fully charge both plate groups. This procedure led to an immediate capacity improvement.

It has been found in other work that in constant potential cycling there will be a very gradual decrease in capacity if the charge conditions are not ideal. One of the most important is the necessity of the high initial in-rush current. This high in-rush and the efficiency of the conversion of nickelous to nickelic hydroxide are related. As has been found in other instances, the higher current density increases the officiency of the reaction. In our apparatus it was not possible to adjust the voltage at the battery terminals and as a result the in-rush current was limited to a certain extent by the obmic resistance of the lead wires and instruments. In constant potential charging the overcharge of the positive plate is of course limited by the full charge of the negative plates. It is most probable that the effect of the decreased positive plate charge efficiency which is an undercharged positive electrode, could have been overcome if the constant potential charge were extended from two to four hours. This point has been substantiated in tests on these batteries by the Chemical Corps. (Ref. 3(1)).

)

Inasmuch as the cycling apparatus was not designed to readily go from two to four hours of constant potential charge, it was decided to use a constant current charge to equalize the plate capacity after every fourteenth cycle. A four hour charge would have required manual control of the cycle. To fulfill other requirements, this would have meant that a Technician would have been needed for a 1:00 A.M. to 5:00 A.M. shift in addition to the long discharge. Since funds were not available and

nothing would have been learned, a constant current charge appeared reasonable. The charge following the discharge to 20.00 volts was done at one ampere overnight.

As an afterthought, the same effect could have been accomplished by carrying the discharge beyond zero (0) volts using an external potential and recharging at constant potential for two (2) hours as was done on cycles 19 and 20.

The tattery cycling from this point to the 177th cycle was routine. Prior to the next cycle, it was necessary to shut off the electric power to the plant to allow electric crews to install new lines to an adjacent factory. After the 188th cycle, the motor generator broke down when new cells for the Chemical Corps being charged from the same source prior to acceptance testing were allowed to reverse the fields of the generator. After repairing the unit, the additional cycles were completed without difficulty.

The electrolyte levels of the cells were adjusted in the charged state after every capacity cycle.

5. CONCLUSIONS

1

The vented nickel-cadmium battery designed for the E-41 miniaturized point source alarm has successfully completed two hundred (200) charge - discharge cycles after which it is still capable of meeting the discharge requirement of 0.5 ampere for 12 hours to 20.00 volts. To fulfill this requirement it is necessary that the battery have occasional prolonged constant potential or regular constant current charge to more fully charge the positive and negative plates. の 100 mm の 100 の

6. RECOMMENDATIONS

In future Contracts, provision should be made for approved procedures to be followed in case of malfunction of the circuit and equipment. For example, there was not clearly defined procedure to be followed after the breakdown of the generator or after power failure.

7. IDENTIFICATION OF TERCONNEL

Name	Title	Time, Hrs.
J. Anderson	Electrical - Chemical Technician	46
S. Januszkiewicz	Project Leader	29

<u>.</u>

The vented nickel-cadmiun better, designed for the night alarm has successfully passed 200-charge-discharge cycles. Those cycles indicated a need for occasional extended constant potential or regular constant current charge to now fully charge the positive and negative plate in a cell.

Rest Circuit "conirements Cycling Test Contract Di--03-6E0-9Z CLILS: 10.11 85273 FTC/D Tivision, Resthampion, ass. -11 VII-Supplementary Report - 31 arch Could-Setional Eatterios, Inc. 2 tebles; 2 drawings (Centract D.-36-039-SC-85273 S. Januszkienicz 12 pp. 1 figure TILLUSTICKIT CADITIC EATT VE 1961

The vented nickel-cadmium battory desirned for the "-th alors has successfully passed 200 chernal district cycles indicated a mood for occasional extended constant potential or regular constant current charge to fore fully charge the positive and negative plate in a cell.

(El 'maject Ho. 3618-03-001)

AD

OUISTITE

OUISTICATION TESTICATION, INC. 1. Requirements
HIGH Division, Testhampton, Test Circuit

UTTO HTGHL-CAD IU. T-L1 ALD. 3. Cycling Test
EATHTY S. Jenuszkiericz h. Contract DASUPPLEMENTARY CPORT - 31 arch 26-039-501961 12 pp. 1 flume - 85273
2 tables; 2 cremins
(Contract A-36-039-50-85273)
(IN Project No. 3618-03-001)

The vented nickel-cadmium battery designed for the T-Li alarm has successfully massed 200 charge - discharge eveles. These cycles indicated a need for occasional extended constant potential or regular constant current charge to nore fully charge the positive and negative plate in a cell.

Could—Tational Batteries, Inc.

1. Requirements
11. Requirements
12. Test Gircuit
13. Cycling Test
14. ALF:
15. Annuszkiericz
15. Surplementer Towat - 31 Tarch
1561 12 pp. 1 figure 1561 12 pp. 1 figure 1561 12 pp. 1 figure 1562 2 tables; 2 cremins
(Contract M-36-039-SC-85273)

The vented nickel—cadmium battery designed for the Tell alerm has successfully bassed 200 charge - dischere cycles. These cycles imitated a need for occasional extended constant potential or regular censtant current charge to more fully charge the positive and negative plate in a cell.

(N/ Project No. 3618-03-001)

And the second of the second o

Gentrect DA-Rest Circuit 3. Ovcling Test Tegui rerents 26-039-SC-85273 الدرية الأنكالي ال TICHD Division, Desthamoton, ass.2. THE TIME THE THE LAND Supplementary Report - 31 arch 1961 12 pp. 1 figure -2 tables; 2 dramings (Centract DA-35-039-SG-85273 Could stienal Batteries, Inc. (DF Troject No. 3618-03-001) FATTER S. Januszkiericz C Link

The vented nickel-eadmium brttory designed for the Lall aler has successfully bessed 200-charge-discharge eyeles. These eyeles indicated a need for occessional extended constant potential or regular constant current charge to rore fully charge the positive and negative plate in a cell.

Rest Circuit Cycling Test Contract Ma-1. Requirements -03-66-032 85273 Could-Matismal Batteries, Inc. FIGAR Division, Resthampton, ass. V-17 D MICHIL-CAD IN TALL AND Supplementary Peport - 31 Parch 1961 12 pp. 1 firme 2 tebles; 2 dravines (Contract Pr-36-039-SC-85273 (El Project No. 3618-03-001) S. Januszkiericz BATTI 1961

-41 elem has successfully passed 200 chara - discorre cycles. These eycles indicated a need for The vented nickel-cadmium battory desirned for the ocursional extended constant potential or require constant current charge to rove fully charge the positive and negetive plate in a cell.

Contract DA-Cycling Test Requirements Test Circuit 26-039-SC-ULIUSSITION 85273 TICED Division, Lesthampton, ass. 2.
THAT DITCELLOND IN THE FLAT 3.
THAT TO LICELLOND IN THE FLAT A. ,-Currlementary cport - 31 arch 1961 12 pp. 1 flure - 2 tables; 2 drawing (Controct 2.-36-039-SC-85273) only letional Patteries, Inc. (3) Project No. 3618-03-001) S. Januszkiericz L. J.L.

j,

1

the state of the successfully ressed 200 charge - discherge oveles. These cycles indicated a need for The ventod nickel-cadmium battery designed for the occisional entended constant potential or regular constant current charge to nore fully charge the ocsitive and megative plate in a cell. cherre cycles.

UNCLASSIFIND ಗೆಬೆಗೆವೆ TIC/D Division, asthamoton, ass.
THITD TOTAL CAD THE -41 ALF: Supplementer, Sport - 31 Erch could stional Batterics, Inc. 1961 12 pp. 1 figure -

T.C. VS. T.L.D

Test Circuit Cycling Test

Contract DA.

-35-6£0-9Z


85273


Tequirements


2 tables; 2 cremins (Contract 74-36-039-SC-85273) (n) Project To. 3618-03-001)

-41 alorm has successfully hassed 200 charge - dis-The vented nickel-eadminn battery designed for the charac cycles. These eyeles indicated a need for occasional extended constant potential or regular constant current charge to nowe fully charge the positivo and negative plate in a cell.


CYCLING TEST 6. 7 A.H. CELLS NO REQUIRED - (2) CHAR MAT PLYWOOD & THICK AFTXBET (1) NOTE - CHAMPER FRONT $_{\cdot}$ $(\dot{\cdot})$) (I) (E) $(\tilde{\mathbf{s}})$ r 2∰ -










667 A H. CELL CYCLING TEST WIRING BACK OF BOARD CON _ DISCHARGE ACTION (A) 10 M G 5ET おしゃ 語り (水) VOUTMETUR(BYES) MOST 1 46 てっさか VOLTV 407-76 7 16 17 6431 7631 36 19 5 17 - A 2 7 6 16 16 16 16 16 6 7 18 1 17 1 A CHOV ACRERMINAL STRIF (JONES) 8-141 RESISTORS (COMMITS) (1) # 1/56 & ACT | 1/50 | ACT | AC BUART 1000 Carron Commence of the Co 10 m 5 (B) # 8700K12 (2 grand ret VALUE PHECSIAT. (0HM17L) = 0312 C CHMS + E HBC AMPS JOHTHOD THURS FOR MG SET #16 WIRE 19 STRAND -1920 SAUTOR CONTACTOR (ECTRY) HHO HO V ALC COLE HIA WIFE -









Gould-National Butteries, Inc. NICAD DIVISION Easthampton, Manuachusetts

Il. September 1963.

References U.S. Amy Signal Research & Development Laboratory Continut No. BA-36-039 10-85171 DA Project No. 3 6 18-05 CO. Sup Tool mary Report

Gent sewers

We are an using the Supplementary Report giving the results of the Lain Cycling Tasts. This is it necessaries with the requirements of Ingala of referenced contract, are modification No. 2 thereto.

Very smily yours,

NICAD DIVISION

Could Notional Batteries, Enc.

F. L. Anderson Chi) Chaganeer

FCA/ses

Enclosuro

DISTRIBUTION LIST SUPPLEMENTARY REPORT DA-36-039 SC-85273

Chief, West Coast Ofc, USASRDL

(1)

75 South Grand Avenue

Pasadena, California

Building 13

OASD (R&E), Ra 32-1065 The Pentagon Washington 25, D.C. (z)ATIN: Technical Iderary Chief of Research & Development OCS, Dept. of the Army (x)Washington 25, D.C. Commander Wright Air Dryslopmert Division Wright-Patterson Airlbree Base, Ohio AUTH WCOST-3 (1)Commanding General U. S. Army Electronic Proving Ground Fort Huachwa, Arizona Darector Almed Services Technical Information Agency Arlington Ball Station Arlington 12, Virgi: is AMIN: MIPDR (5) Commanding Officer U. S. Army Signal Materiel Support Agency Fort Monmouth, New Jersey ATTN: SIGRA/SL-ADJ (1)U. S. Continental Army Command Liaison Office U. S. Army Signal R&D Laboratory Fort Monmouth, New Jersey Commanding Officer U. S. Army Signal R&D Laboratory Fort Monmouth, New Jersey ATTN: SIGRA/SL-P ATTN: SIGRA/SL-PS ATTN: SIGRA/SL-LNS SIGRA/SL-INR ATTN: Dir of Res or Engrg A'TTN : ATIN: Tech Document Center